



## Torneira de Serviço – Zero Fugas de 5/16"



- Very efficient tightness that guarantees no gas leaks
- Extremely reduced volumes that prevent gas leaks during the valve connecting or disconnecting phase
- Very easy to handle
- Allow to regulate the refrigerant flow
- Prevent the burning risks to fingers when disconnecting
- Constructive precision that guarantees 100% compatibility with the systems on the market
- PTFE seal compatible with CFC, HCFC and HFC
- Available in 1/4"SAE and 5/16"SAE versions

Distribuição de Equipamentos e Acessórios

